



Display
Adjustment the Oxy %

P1 : Adjust Oxy % : Counter clockwise = Oxy % will be higher.
Clockwise = Oxy % will be lower.

P2 : Do not adjust

!!! ATTENTION !!!
Lambda Sensor must be in free air 5 min. before adjustment
Display must show between 20 - 21 %



RS 485 Cable type
fx. BELDEN 8761 1 x 2 x 22 AWG shielded

PE

Firma	Dato	Navn	El diagram	Side
Pricatech, Tlf. 97 91 15 57	2021			
Reference	Rev. dato	Diagram nr.	PCT 254	1
TTH / KH	2021	PCT 254		